CoG −200. mm from moving flange




CoG −100. mm from moving flange
Actuator 1
Actuators 1 (b) and 2 (r), Θ=60
Actuators 3 (b) and 4 (r), Θ=60
Actuators 6 (b) and 6 (r), Θ=60
F/W
γ
0.8
0.6
0.4
0.2
0
−0.2
−0.4
−0.6
−0.8
0
100
200
300

CoG 0. mm from moving flange



CoG 100. mm from moving flange



CoG 200. mm from moving flange