






Tooling ball differences





Balls at 0 degrees





Balls at 45 degrees



Balls at 90 degrees



Balls at 135 degrees



Balls at 180 degrees

